CW5045



INFORMATION IS SPECIFIC TO OUR PRODUCTS AND CAN CAUSE
DAMAGE IF USED WITH NONE COMPATIBLE PRODUCTS SO PLEASE
CHECK WITH YOUR SUPPLIER FOR COMPATIBILITY

These drawings are supplied as a guide no guarantees are implied or given. Caution when wiring and check with a qualified professional if unsure. Documentation will be updated amended at the discretion of CNC4YOU Ltd.



Stepper Motor Driver

CW5045 2-Phase stepping Motor Driver



CNC4YOU Ltd.



CW5045 2-Phase Mircostepping Motor Driver

Characteristics:

- 1. Power input type: 20VDC~50VDC
- 2. Output current: 1.5A 4.5A
- 3. 100 Volt Advanced HEXFET® Power MOSFETs from International Rectifier utilise advanced processing techniques to achieve extremely low on-resistance per silicon area reducing heat and transferring more power to your stepper motor so allowing drivers to run cooler. The 100Volt output and max current of 33Amps hopefully will allow better fault tolerance than your average controller.
- 4. Microstepping with both imperial and metric step rates for ease of setup depending on the pitch of your ballscrew or trapezoidal screw or similar:

Imperial: 1/2, 1/4, 1/8, 1/16, 1/32, 1/64, 1/128, 1/256,

Metric: 1/5, 1/10, 1/25, 1/50, 1/125, 1/250.

- 5. Over temperature shutdown protection.
- 6. Automatic half current option for power saving and reduction in standby temperature
- 7.. Stepper motor wiring error protection to protect against phase polarity errors.
- 8. The maximum pulse rate is 100KHz compatible with Mach 3 motion control software.
- 9. Working environment: Temperature -15 ~ 40 Humidity<90%.

I/O Pin Description:

- 1. VCC+: DC power supply positive connection.
 - Note: Must guard against exceeding 50V, to avoid damaging the module
- 2. GND: DC power supply negative connection.
- 3. A+, A-: Stepping motor phase one winding
- 4. B+, B-: Stepping motor phase two winding
- 5. PUL+, PUL-; Stepping pulse input+5V (Positive edge effective, pulse duration>10 μ Sec) .
- 6. DIR+, DIR-: Stepping motor direction input, high -> forwards, low -> reverse.
- 7 .ENA+, ENA-: Enable motor input. Leave open if not required.

NOTE:

- 1. If ambient temperature is high or working current over 2.7A, fix the module on metal plate, or use Axle fan to remove the heat, this will extend working life of the module.
- 2. Half current automatically: if no control signals are received for half second, driver will enter half current state automatically for power saving mode,
- 3. The protecting circuit within this driver, will help protect module when users connect stepper winding incorrectly, the driver will normally self protect but stepper will run abnormally, shake, and output current is reduced. Please switch off instantly and check the wiring of the machine.


CNC4YOU Ltd.



CW5045 2-Phase Mircostepping Motor Driver

Control Signal Connector Interface

VCC	R
5V	0
12V	680Ω
24V	1.8ΚΩ



CNC4YOU Ltd.

CNC4YOU.co.uk

DIP SWITCH SETTINGS

SW1	SW2	SW3	Current (A)	
ON	ON	ON	1.5	
OFF	ON	ON	2	
ON	OFF	ON	2.4	
OFF	OFF	ON	2.8	
ON	ON	OFF	3.2	
OFF	ON	OFF	3.7	
ON	OFF	OFF	4.2	
OFF	OFF	OFF	4.5	


SW4 OFF = HALF CURRENT SW4 ON = FULL CURRENT

SW5	SW6	SW7	SW8	Microstep
ON	ON	ON	ON	2
ON	OFF	ON	ON	4
ON	ON	OFF	ON	8
ON	OFF	OFF	ON	16
ON	ON	ON	OFF	32
ON	OFF	ON	OFF	64
ON	ON	OFF	OFF	128
ON	OFF	OFF	OFF	256
OFF	ON	ON	ON	5
OFF	OFF	ON	ON	10
OFF	ON	OFF	ON	25
OFF	OFF	OFF	ON	50
OFF	ON	ON	OFF	125
OFF	OFF	ON	OFF	250
OFF	ON	OFF	OFF	DISABLE
OFF	OFF	OFF	OFF	DISABLE

CNC4YOU Ltd.

CNC4YOU.co.uk

4 Installation dimension



CNC4YOU Ltd.